
# PRESENTATION PREPARED FOR WOODLAND JOINT UNIFIED SCHOOL DISTRICT



PURPOSE

DIRECTION

**ADOPTION** 





STRATEGIC COMMITTEES

SITE INTERVIEWS

DISTRICT PLANNING COMMITTEE

SITE ASSESSMENTS

CREATION OF A DRAFT PLAN

SITE VISITS

BOARD REVIEW AND DISCUSSION

BOARD DECISIONS ON DIRECTION AND ADOPTION

Dec 6, 2010- Dec 13, 2010

Mar 1-23, 2011; June 10-14, 2011

Nov 29, 2010; Jan 10, 2011

Feb 2011-May 2011

July 14, 2011

Aug-Oct 2011

Aug 25, 2011; Oct 13, 2011; Oct 27, 2011

Dec 2011





## WE NEED A MASTER PLAN TO:

- Provide facilities that are safe and secure for students and staff
- Protect District assets and address potential liabilities from accidents and Americans with Disability Acts claims
- Provide facilities with adequate restrooms
- Provide facilities that are energy efficient and sustainable to minimize impact on the general fund



#### SESSION NO. 4 GOALS:

- 1. Provide information and recommendations as to the necessary improvements to protect District assets
- 2. Solicit direction from the board for finalizing the scope of improvements at each site
- 3. Identify most urgent needs at each campus and directions for implantation
- 4. Adopt overall master plan / or advise on corrections that are required
- 5. Identify immediate projects the board of trustees would like to move forward
- 6. Identify any next steps to be taken





#### IMMEDIATE NEEDS OR AREAS ADDRESSED:

- 1. ADA upgrades hardware, stairs, handrails, lifts, etc.
- 2. Safety issues tripping hazards, exposed electrical lines, hazards, crosswalks, non-working intercom systems, fire alarm systems, Non-DSA approved structures, damaged lockers, non code compliant kitchen equipment.
- 3. Asset protection drainage problems, failing roofs, water intrusion, failed paving, failing covered walkways, failing stadium concrete
- 4. Essential student comfort—failing HVAC systems, failing lighting, ventilation of restrooms, broken tile replacement, repair to damaged walls upgrading restrooms for compliance.
- 5. Basic energy / water conservation HVAC system replacement where required due to age or failure, replacement of irrigation systems.





## **Beamer Park Elementary School**

\$92,21 <u>5</u>
\$12,500
\$180,000
\$7,500
\$8,120
\$3,553
\$25,500
\$107,180
\$5,000
<del>\$263,060</del>
\$25,316
\$100,000
\$77,050
\$85,250





<b>Charles</b>	<b>E</b> .	<b>Dingle</b>	Elementary	/ School
			_	

Subtotal	\$1,002,340
Replace HVAC at permanent buildings	<u>\$410,480</u>
Restroom modernization	\$307,500
ADA accessibility upgrades	\$100,000
Storm drain/ alleviate alley-way flooding	\$100,000
Rubberized play surface for all existing/new playgrounds	\$84,360

## **Gertrude S. Freeman Elementary School**

Slurry coat and restripe AC paving	<del>\$76,133</del>
Rubberized play surface for all existing/new playgrounds	\$86,400
Storm Drain/ alleviate flooding near trash containers	\$100,000
ADA accessibility upgrades	\$100,000
Provide new carpet in administration	\$4,095
Restroom modernization	<del>\$331,500</del>
Subtotal	\$698,128





## William B. Gibson Elementary School

\$3,040 \$257,346 \$304,290
• •
ψ9,040
\$9,040
<del>\$405,000</del>
\$100,000
\$100,000
\$44,850
<del>\$134,638</del>
\$387,536
\$678
\$10,000





Ruhnau Ruhnau Clarke

## **Rhoda Maxwell Elementary School**

<u>Ψ10,000</u>
\$10,000
\$40,696
\$142,436
\$100,000
\$205,200
\$188,654
\$2,278



Subtotal	\$1,957,567
Provide exterior lighting and emergency power	<b>\$139,175</b>
Replace roofing throughout campus	\$94,064
Replace HVAC system throughout campus	\$539,140
Restroom modernization	\$323,250
ADA accessibility upgrades	\$100,000
Add additional sidewalks for safety	<del>\$38,742</del>
Rubberized play surface for all existing/new playgrounds	\$77,200
Slurry coat and restripe AC paving	\$93,661
Hardcourt AC paving	\$89,512
Planting, playfield irrigation and trees	\$462,823

## Ramon S. Tafoya Elementary School

Subtotal	\$238,825
Rubberized play surface for all existing/new playgrounds	\$37,200
Slurry coat and restripe AC paving	\$201,625





## T.L. Whitehead Elementary School

Remove landscape and irrigation system and prep site	\$2,823
Slurry coat and restripe AC paving	\$195,353
Rubberized play surface for all existing/new playgrounds	\$100,700
Replace/provide parking lights for safety	<del>\$49,478</del>
ADA accessibility upgrades	\$100,000
Replace roofing campus wide	\$299,672
New controls for HVAC system	\$35,000
New public address system	<b>\$103,885</b>
Subtotal	\$886,911



## **Woodland Prairie Elementary School**

Slurry coat and restripe AC paving	<del>\$142,157</del>
Rubberized play surface for all existing/new playgrounds	\$169,700
ADA accessibility upgrades	\$100,000
Replace failing carpet/flooring	<del>\$167,339</del>
Restroom modernization	\$472,884
Replace fire alarm and intrusion system campus wide	\$167,339
Replace HVAC system campus wide	\$1,338,708
Replace roof system campus wide	\$305,688
Replace covered walkways system	<del>\$496,580</del>
Subtotal	\$3,360,395





Zamora Elementary School	
Planting, playfield irrigation and trees	\$299,950
Slurry coat and restripe AC paving	\$201,696
Rubberized play surface for all existing/new playgrounds	\$123,500
ADA accessibility upgrades	\$100,000
Re-paint buildings	\$26,025
Replace campus clock system	\$71,388
Provide new public address system	\$124,929
Subtotal	\$947,488
Sci-Tech Academy	

Planting, playfield irrigation and trees	\$650,000
Rubberized play surface for all existing/new playgrounds	\$96,300
ADA accessibility upgrades	\$100,000
Restroom modernization	\$191,250
Replace HVAC system throughout campus	\$554,344
Replace roof throughout campus	<b>\$158,384</b>
Subtotal	\$1.750.278





## **Douglass Middle School**

Slurry coat and restripe AC paving	\$270,790
Address crosswalk safety issues	<del>\$5,000</del>
ADA accessibility upgrades	\$175,000
Replace gymnasium flooring and sound system	\$546,696
Replace roofing throughout campus	\$771,240
Upgrades to HVAC system throughout campus	\$1,446,075
Replace door hardware throughout campus	\$318,000
Restroom modernization	\$343,117
Subtotal	\$3,875,918





## **Lee Middle School**

Subtotal	\$2,293,949
Replace damaged in-wall lunch tables	\$192,000
Replace intercom system throughout campus	\$151,970
Replace roofing and covered walkway throughout campus	<del>\$788,704</del>
Gymnasium – replace bleachers and HVAC	<del>\$326,800</del>
Classroom building M restroom modernization	\$366,375
ADA accessibility upgrades	\$250,000
Replace above ground vaults	\$200,000
New hardcourt striping	\$1,000
New AC paving at hardcourts	\$17,100

## **Pioneer High School**

Repair roof leaks around the campus	\$159,090
Subtotal	\$159,090





## **Woodland High School**

Woodiana mgm comoci	
AC paving replacement at staff parking	\$16,258
Irrigation replacement throughout campus	\$1,060,089
Replace unsafe/ exposed transformer	<del>\$36,000</del>
Storm drain/ alleviate electrical flooding at agricultural area	\$200,000
ADA accessibility upgrades	\$250,000
Replace gymnasium flooring, bleachers, lighting, exhaust at lockers	\$929,702
Replace student lockers throughout campus	\$78,000
Replace HVAC systems throughout campus	\$4,252,276
Replace roofing throughout campus	\$1,214,936
New concession/ toilets at football stadium	<del>\$545,000</del>
New football stadium bleachers/ press box	\$1,275,000
Subtotal	\$9,857,261






Cache Creek High School	
Planting, playfield irrigation and trees	\$334,372
Parking AC paving, hardcourt AC paving, concrete paving, curb and gutter	\$262,830
Parking/ hardcourt restriping	<del>\$847</del>
ADA accessibility upgrades	\$150,000
Restroom modernization	\$215,625
Re-roofing of permanent buildings	\$180,356
Replace HVAC system throughout campus	\$476,448
Upgrade science lab for minimum program needs	<del>\$221,760</del>
Subtotal	\$1,842,238
Woodland Adult Education	
Slurry coat and restripe AC paving	<del>\$16,245</del>
ADA accessibility upgrades	<u>\$100,000</u>
Subtotal	\$116,245





\$32,421,519

**Total – All Schools** 



Water Intrusion



Inadequate storage



Existing kitchen mold issue



Career tech areas




Restroom with water intrusion



Existing science labs at Woodland High School






Deteriorated walls at restrooms




Cracked and unleveled concrete



Inefficient windows



Non-ADA compliant handrails



Vent at existing kitchen



Non-DSA approved structures





Outdated benches



No handrails provided



Tripping hazard



Inefficient air distribution



Water intrusion



No sawdust collection at equipment





Hole at concrete walk



Debris in classrooms



**Damaged Lockers** 

Water Intrusion



Inefficient windows



Water Intrusion







Improper wiring for technology



Unsafe storage areas



Cracked and deteriorated paving



Deteriorated inefficient landscaping




Unsafe conditions at Lee



Potholes at paving







Tripping hazard at sidewalk



Deteriorated ceiling conditions



Water intrusion at ceiling



Water intrusion/inefficient air distribution




Non-DSA approved structure



Inefficient / no lighting








Heaved concrete at building




Broken missing tile



No finish at interior wall



Outdated technology




Tree and building conflict




Non-ADA compliant handicapped stall








Electrical wire management



Hazardous/dirty conditions at kitchen



Deteriorated tile where partitions replaced




Non-ADA compliant door



Exterior exposed coolers and freezers do not meet DSA requirements for restraint of walls







Poorly lit hallways


MPR too small for student population



Water intrusion



Inefficient / outdated kitchen equipment



Hole in exterior plaster




Non-NSF approved equipment








Exposed electrical wires



Non-ADA hardware




Non-ADA accessible doors/stairs



Improper conduit management




Failing deck at covered walking



Rust at steel canopy








Non-ADA pluming



Rigid connection between separate structures



Electrical vault with exposed wires



Missing tiles



Heaving paving



Plants growing on roofs







Inefficient lighting




Cracked masonry




Water runoff issue



Wire management issues



Broken planters



Lack of insulation







Existing ceiling conditions



Classrooms do not meet Title 5 requirements




Outdated inefficient boiler



Exposed high voltage transformer



Poor conditions at playfield



Existing kitchen with inadequate serving space







Broken lighting at stadium




Existing science sink



Settlement at existing press box



No caulking or sealant at joints



Heaved concrete at stadium



Exposed rebar at stadium







Landscaping and earth above finish floor level




Shower and locker room



Cracked concrete at stadium



Lockers



Existing bike rack



"Green House"


DECEMBER 8, 2011







**Existing lockers** 



Non-existing. landscaping / lack of handrails



Water intrusion in science classrooms



Water intrusion at ceiling




Water intrusion



Lack of wing space, theatrical lighting, catwalk and ADA access






Holes in exterior walls and deteriorated plaster



**Deteriorated landscaping** 




Cabinets not usable



Non-ADA compliant doors



Asphalt needs replacing



Improper suspension / bracing of equipment





Poor / Non-existent drainage


Poor or inadequate lighting



Trophies displayed on electrical equipment



Non-code compliant wiring



Deteriorated ramps



Inadequate kitchen facility







Non-compliant kitchen



Outdated technology



Outdated technology



Poor teaching / learning environment



Inefficient windows and leaking roof



Unsafe storage of chemicals







Non-DSA Structures



Lack of space at stage



Non-DSA structure




Inefficient energy lighting controls




Holes in walls







Water Intrusion



Fields in poor condition



Failing roofs



Roof structure failing



No handrails



- 1. Implement improvements to protect District facility assets.
- 2. Address issues related to safety, security, and adequacy of restrooms (lighting, heating, cooling).
- 3. Develop a pilot project that demonstrates the approach for the master plan. Approach will be to select the project, members for oversight committee, complete project on time and within budget. Communicate results to the community. Possible projects, M.P.R. at Zamora, Cache Creek High, Willow Spring Elementary site, New K-8, stadium at Woodland High School.
- 4. Adopt Master Plan as an interim study to be updated in 2 years once funding capabilities become more clear.

